

# Inspection Report: Property Summary



This summary is not the Asbestos Register and can not be relied upon on its own. The Asbestos Register will always override the summary. Please read the Asbestos Register in its entirety.

## Yarriambiack Shire Council - Hopetoun Asbestos Building Summary 2021 Colour Coded Priorities

### 1. Immediate Action Required

Re-audit Due AA Ref#

HOPETOUN	3396	VIC	Hopetoun CFA Shed	62 Lascelles Street	27-01-22	62069	
HOPETOUN	3396	VIC	LB58C Tennis Court Clubrooms	4 Austin Street	27-01-22	62082	
HOPETOUN	3396	VIC	LB69 Tip Hopetoun	8 Tip Road	27-01-22	62083	
HOPETOUN	3396	VIC	LB72 Depot	92 Cumming Street	27-01-22	62066	
HOPETOUN	3396	VIC	LB77 Memorial Hall	13 Austin Street	27-01-22	62071	
HOPETOUN	3396	VIC	LB82 Aerodrome	78 Hopetoun Aerodrome Road	27-01-22	62062	
HOPETOUN	3396	VIC	LB86 Corrong Homestead	Evelyn Street	27-01-22	62065	
HOPETOUN	3396	VIC	LR33 Caravan Park	6194 Henty Highway	27-01-22	62064	
HOPETOUN	3396	VIC	Old Powerhouse (Depot)	51 Lascelles Street	22-01-22	62061	

### 2. Asbestos Present (High)

Re-audit Due AA Ref#

HOPETOUN	3396	VIC	LB119 Recreation Reserve	29 Strachan Street	27-01-22	62073	
HOPETOUN	3396	VIC	LB58A Swimming Pool	4 Austin Street and 54 Evelyn Street	27-01-22	62080	
HOPETOUN	3396	VIC	LB58B Bowling Club	4 Austin Street and 54 Evelyn Street	27-01-22	62063	
HOPETOUN	3396	VIC	LB58D Scout Hall	54 Evelyn Street	27-01-22	62075	
HOPETOUN	3396	VIC	LB58E RSL Hall	Austin Street (next to swimming pool)	27-01-22	62074	
HOPETOUN	3396	VIC	LB96 Shire Depot	74-76 Cumming Street	27-01-22	62078	

### 3. Asbestos Present (Medium)

Re-audit Due AA Ref#

HOPETOUN	3396	VIC	LB74A Preschool	87-89 Mandeville Street	27-01-22	62072	
----------	------	-----	-----------------	-------------------------	----------	-------	--

### 4. No Asbestos Found

Re-audit Due AA Ref#

HOPETOUN	3396	VIC	LB60 Shire Offices	75 Lascelles Street		62079	
HOPETOUN	3396	VIC	LB73 Illuka Depot	Garrard Street		62070	
HOPETOUN	3396	VIC	LB82 Shire Depot	68 Hopetoun Aerodrome Road		62077	

# Inspection Report: Property Summary

This summary is not the Asbestos Register and can not be relied upon on its own. The Asbestos Register will always override the summary. Please read the Asbestos Register in its entirety.



Re-audit Due AA Ref#

## 1. Immediate Action Required

Re-audit Due AA Ref#

HOPETOUN	3396	VIC	LB90 Senior Citizens	20 Dennys Street	27-01-22	62076	
----------	------	-----	----------------------	------------------	----------	-------	--