



NOTES

01. Upgraded north-west entry (signage and safety rails)

02. Upgraded entry (fencing, vehicle and pedestrian gates)

03. Remove the existing play node and Charles Ayrey Pavilion. Re-develop a new play facility outside the fencing of the new bank of courts

04. New electronic scoreboard (operated from the community pavilion)

05. Aluminium bench seats around the oval

06. Covered deck to provide an entry and an additional gathering space to the western side of the community pavilion

07. Demolish the former kitchen/social room. Replace with an open gathering area with barbecue

08. Updated central amenities building

09. Indoor sports facility upgrade (synthetic grass and retractable netting)

10. Indoor sports facility - northern entry hard surface upgrade
11. Indoor sports facility - external wall enhancement (art and/or murals)

12. New storage facility

13. Remove the former CFA training facilities

14. Additional wind break trees

15. Updated eastern amenities building

16. Oval upgrade (re-shaping, irrigation, drainage, goal catch nets and recycled plastic picket fencing)

17. Grandstand upgrade (transparent wall panels)

18. New 2-net cricket practice facility

19. Covered hard surface spectator zone

20. Remove the southern bank of tennis courts

21. Suitable barrier (such as mass planting or fence screens)

22. Restrict unnecessary vehicle access on the western side of the oval.

DISCLAIMER: THE INFORMATION REPRESENTED IN THIS MASTER PLAN IS SHOWN INDICATIVELY AND IS SUBJECT TO FURTHER APPROVALS, DESIGN DEVELOPMENT, ENGINEERING ADVICE, SITE SURVEY AND FUNDING.